


Allentown, PA:	800-383-8894	Jacksonville, FL:	800-828-3055
Baltimore, MD:	888-601-7500	Little Rock, AR:	833-424-8944
Boston, MA:	800-854-5310	Portland, ME:	800-325-4253
Concord, NC:	800-438-2250	Richmond, VA:	866-839-3495
Delmar, DE:	866-486-1400	Scranton, PA:	800-569-1400
Des Moines, IA:	888-673-5011	Springfield, MA:	800-854-5306
Elkton, MD:	800-544-7127	Voorhees, NJ:	866-315-0235

800-232-6535 *FINANCING AVAILABLE



Length :		54' to 219' with bumper	
Width :		☒	102"
Steering axles :		☒	3
Suspension :		☒	Turner HT-250U
☒ Scale-O-Matic		☒	COLAS Valve
☒ Shut-off valve			
Steering mecanism :			
☒ Forced steer with front turn table			
☒ Suspension and axles with turn tables			
Steering control :		☒ Automatic	☒ Manual
☒ 13 HP Honda power pack			
Axles :		☒	D-22
Axle track :		☒	Other : 79
Brake type:		☒	Drum brakes
Seals :		Stemco Guardian HP	
Bearings :		Stemco	
Brake Chambers:		TSE 30/30T	
Automatic Slack adjuster :		☒	TSE
Brake valve :		Rockwell Wabco	
A.B.S. Brake :		☒	2S/1M
☒ Blue wire on first axle		☐ A.B.S. Plug	☐ Y ☒ N
Hubs :		☒	Dura Light 8 studs steel piloted hubs
Drums :		☒	Standard
		☐	Centrifuse
Rims :		Qty :	<u>12</u>
☒ 17.5 x 6.75		☒	Alum. machined finish
Tires :		Qty :	<u>12</u>
Model: Michelin XTA2 ENERGY		Size : 245/70R17.5	
☒ Plastic spacer (rim & rim)		☒	Plastic spacer (hub & rim)
Tire carrier Témisko Fab :			
☒ 1		☒	C/S
Hubodometer :		☒	None
Location :			
Paint :		Colour :	Black
Colour code:		RAL 9005	☒ Tape 100%
Trim :		☒	None
Rim :		☒	Natural
Rack :		☒	None

Visual lock indicators for inter beam locking
Aluminum checkerplate on front coupler, Aluminum checkerplate front fenders
(4) supports for air and hydraulic lines/beam
Power pack in aluminum box on R/S
Double redundant hydraulic steering circuit.
On board steering control, Plug in remote control and wireless remote control (Lodar) + antenna
dual Hydraulic drop leg to facilitate extending
"D" rings on each side of the front and rear loading platforms, total of 2X loading bunks
180 ft of hydraulic lines from front to back
Oversized sign at rear

Specifications are believed to be correct, but may contain errors and/or omissions. Photographs are the representative of the subject equipment but may not be identical.
Equipment availability, prices and specifications are subject to change without notice.